TECH - NOTE

UNION BRASS MANUFACTURING COMPANY




INDUSTRIAL SUPRVALVETM


WASHERLESS VALVES















Open





INDUSTRIAL SUPERVALVETM Operation



- Two polished CERAMIC DISKS are aligned in an open position to provide full water
- * Brass Stops



A 1/4 Turn allows the upper disc to close or shear off water flow in a scissor-like



The ceramic discs are chemically inert and will not react to chemicals and lime.



The SUPERVALVE contains no washers or springs.




* The SUPERVALVE is perfect for all water conditions



* Ten year limited warranty, against factory defécts.



* Flow rate unrestricted is 6.8 GPM at 75 PSI.



Simple 1/4 turn for full on and full off

For more information contact:

UNION BRASS MANUFACTURING COMPANY

2955 Lone Oak Circle, Eagan, MN 55121 Phone (651) 454-8858 Fax (651) 454-1228 WWW.UNIONBRASS.COM